

Bluff Villas Regime #55, HPR Copper Ball Valve Replacement Program

1. Have your plumber install new copper ball valves on each main water supply line (hot and cold) and conspicuously label the locations.
2. Submit a copy of your plumber's bill to Bluff Villas Regime #55, HPR % IMC Resort Services, Inc. for reimbursement.
3. Bluff Villas Regime #55, HPR will reimburse the owner for the plumber's portion of the bill only. Any cosmetic drywall repairs are solely the responsibility of the condo owner.

Bluff Villas Regime #55, HPR
% IMC Resort Services, Inc.
2 Corpus Christie Pl #302
Hilton Head Island, SC 29928

Attention: Bryan Dorshimer